## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,861,290 B1

Page 1 of 1

DATED

APPLICATION NO.: 09/699537

INVENTOR(S)

: March 1, 2005 : Walter L. Moden

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## On the title page:

In ITEM (56) "References Cited,

U.S. Patent Documents,"

COLUMN 1,

LINE 15,

insert --5,454,161

10/1995

Beilin et al .--

COLUMN 2,

LINE 17,

insert --6,165,766

07/2001 Moden--

COLUMN 4,

LINE 19,

change "C4solder" to --C4 solder--

Signed and Sealed this

Twenty-eighth Day of August, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office